

Work Order (Bid Form)

AUDITOR: J SUMMERS 615-473-2343 JSUMMERS@UNITED.NET



WORK ORDER INFORMATION

Work Order Name: WO/90009MD2664/1

Work Order Type: Weatherization Audit Name: 90009MD2664

CLIENT INFORMATION

Client Name: Address:

37203 Client ID: 90009MD2664

Alt. Client ID: DAVIDSON

AGENCY INFORMATION

Agency: Metropolitan Development and Housing Agency **Agency Phone:** (615) 252-8500

Address: 701 South Sixth Street Fax: (615) 252-8533

> Nashville, TN 37206 **Email Address:**

Company Name & License Number:	
Contractor's Signature:	

COMMENT

SITE BUILT: 1940

LEAD AND ASBESTOES MAY BE PRESENT

Measure 1 Seal	Ducts			Componen	ts			Inspected
Comment DUCT S	EALING MEASURES:							
2.) MAS	TIC SEAL FLOOR DUC ^T TIC SEAL FLOOR RETU TALL AIR FILTER, LEAV	JRN AND	JOINT	S				
				Estimated	<u>!</u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10 Miscellaneous Su	Duct Sealing	Each	1					
Other Detail						1		
			Measur	e Sub Total:			Sub Total:	
Measure 2 Infilt	ration Redctn			Componen	ts			Inspected
2.) WS/I 3.) REH 4.) WS/I 5.) SEAI 6.) WS/I	DS / SEAL INTERIOR D DS FRONT, BACK, AND ANG FALLEN DRYWAL DS DOOR TO ATTIC L PLUMBING PENETRA DS 2 KNEEWALL ACCE TALL CHIMINEY BALLOC	SIDE DO L IN FINIS TIONS KI	ORS SHED / ITCHEI RS.	N AND BAT			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Miscellaneous Su	Infiltration Reduction	Each	1					
Other Detail								
			Measur	e Sub Total:] ,	Sub Total:	
Field Notes:								

Client Name:
Client ID: 90009MD2664
Alt. Client ID: DAVIDSON

Work Order Name: WO/90009MD2664/1 Report Run On: 4/9/2012 Version 8.6.0 Page 2 of 5

Measure 3 DWI	H Tank Insulation			Componen	ts			Inspecte
Comment 40 Gal	Elec.							
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Hot Water Equip	DHW Tank Insulation	Each	1					
2 Labor	DHW Tank Insulation	Each	1					
Other Detail								
]	0.4.7.4.4	
			Measur	e Sub Total:		,	Sub Total:	
	H Pipe Insulation			Componen				Inspecte
Comment First 5 F	- Ft.	Unite	Ofv	Estimated		Oftv	Actual	
Comment First 5 F # Material / Labor	Tt. Description / Comment	<i>Units</i> Each	Qty 1	•		Qty		Inspecte Total
Comment First 5 F # Material / Labor 1 Insulation	Description / Comment DHW Pipe Insulation	Each	1	Estimated		Qty	Actual	
Comment First 5 F # Material / Labor 1 Insulation 2 Labor	Tt. Description / Comment			Estimated		Qty	Actual	
Comment First 5 F # Material / Labor 1 Insulation	Description / Comment DHW Pipe Insulation	Each	1	Estimated		Qty	Actual	
Comment First 5 F # Material / Labor 1 Insulation 2 Labor	Description / Comment DHW Pipe Insulation	Each	1	Estimated		Qty	Actual	
Comment First 5 F # Material / Labor 1 Insulation 2 Labor	Description / Comment DHW Pipe Insulation	Each	1	Estimated			Actual	
Comment First 5 F # Material / Labor 1 Insulation 2 Labor	Description / Comment DHW Pipe Insulation	Each	1	Estimated Unit Cost			Actual Unit Cost	
Comment First 5 F # Material / Labor 1 Insulation 2 Labor Other Detail	Description / Comment DHW Pipe Insulation	Each	1	Estimated Unit Cost			Actual Unit Cost	

Report Run On: 4/9/2012

Measure 5 Floor Ins. R-19					Components F1				
C	omment FLOOR	JOISTS: 2 X 8 X 16 (B	SMT)						
				Estimated					
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	Floor Insulation - Fiberglass Faced Batt - R-19	SqFt	1362					
2	Labor	Floor Insulation - Fiberglass Faced Batt - R-19	SqFt	1362					
0	ther Detail						,		
				Measure	Sub Total:			Sub Total:	
	omment REPLAC	igerator Rplcmnt CE WITH 20 Cuf ENERG IIT FROM PREMISES AS		RATED		EZER, RE LINES.	EMOVE	Actual	Inspected
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Oty	Unit Cost	Total
			Each	Q ιy	Omit Cost	TOtal	Qty	Onit Cost	TOtal
10	Refrigerators	any - any	Lacii	'					
0	ther Detail						7		
L									
				Measure	Sub Total:] ;	Sub Total:	
	Field Notes:								

Report Run On: 4/9/2012

Measure 7 PressureRelief Piping Needed			ded	Components			Inspected		
C	omment AS PER	DOE / MDHA GUIDELI	NES						
					Estimated	1		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	Pressure relief piping	Each	1					
2	Labor	Labor	Each	1					
(Other Detail						1		
L									
				Measur	e Sub Total:] ;	Sub Total:	
	Field Notes:							-	
L									
			Work Or	rder Gra	nd Total:		Gran	d Total:	

Report Run On: 4/9/2012